

**FRONT END ACCESSORY DRIVE (FEAD) BELT
NOISE—VEHICLES BUILT PRIOR TO 6/1/2004—6.0L
ENGINE**

TSB 04-14-12

FORD:

2003-2004 Excursion, F-Super Duty

ISSUE

Some 6.0L equipped vehicles built before 6/1/2004 may exhibit excessive front end accessory drive (FEAD) belt noise when starting the engine cold. The noise is typically described as a squeal or squawk.

ACTION

To service, replace the FEAD belt.

PART NUMBER	APPLICATION
3C3Z-8620-BC	F-Series - Dual Generator (1 OF 2)
3C2Z-8620-HB	F-Series - Dual Generator (2 OF 2)
3C3Z-8620-DB	F-Series - Single Generator
3C7Z-8620-AC	Excursion

WARRANTY STATUS: Eligible Under Provisions Of
New Vehicle Limited
Warranty Coverage

OPERATION	DESCRIPTION	TIME
041412A	Replace Front End Accessory Drive Belt (FEAD) Single or Dual Generator	1.2 Hrs.

DEALER CODING

BASIC PART NO.
8620

CONDITION
CODE
14

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.