

FORD:

2000-2004 Mustang
 2000-2005 Crown Victoria, Taurus
 2000-2003 Explorer Sport, Windstar
 2000-2004 Ranger
 2000-2005 E-Series, Excursion, Expedition,
 Explorer, F-150, F-Super Duty
 2001-2005 Escape, Explorer Sport Trac
 2004-2005 Freestar
 2005 Escape Hybrid
 2004-2005 F-650, F-750

LINCOLN:

2000-2002 Continental
 2000-2005 LS, Town Car, Navigator
 2003-2005 Aviator

MERCURY:

2000-2005 Grand Marquis, Sable,
 Mountaineer
 2004-2005 Monterey
 2005 Mariner

ISSUE

A service kit is now available to improve safety belt retraction speed.

ACTION

See the part application chart and select the appropriate kit. Follow the Instruction Sheet included in the kit. Refer to Workshop Manual Section 501-20a for additional information.

NOTE

IF TEFLON TAPE IS ALREADY PRESENT ON THE SAFETY BELT GUIDE RING (D-RING), DO NOT CONTINUE WITH THIS TSB.

NOTE

EACH KIT SERVICES TWO (2) BELTS.

NOTE

DOES NOT APPLY TO AVIATOR/EXPLORER 4DR/MOUNTAINEER FRONT SAFETY BELTS FOR VEHICLES BUILT AFTER 6/25/2004, OR REAR SAFETY BELTS FOR VEHICLES BUILT AFTER 10/22/2004, BECAUSE TEFLON TAPE IS INSTALLED DURING PRODUCTION.

PART APPLICATION CHART	
Part Number	Application
YR3Z-63611D70-AA	MUSTANG
XW4Z-63611D70-AA	LINCOLN LS
XW4Z-63611D70-AA	E-SERIES
3L2Z-78611D70-AB	CONTINENTAL
3L2Z-78611D70-AB	CROWN VICTORIA
3L2Z-78611D70-AB	EXPEDITION
3L2Z-78611D70-AB	EXPLORER SPORT
3L2Z-78611D70-AB	EXPLORER SPORT TRAC
3L2Z-78611D70-AB	EXCURSION
3L2Z-78611D70-AB	ESCAPE
3L2Z-78611D70-AB	ESCAPE HYBRID
3L2Z-78611D70-AB	FREESTAR
3L2Z-78611D70-AB	F-SERIES SUPER DUTY
3L2Z-78611D70-AB	F-150
3L2Z-78611D70-AB	F650/F750
3L2Z-78611D70-AB	GRAND MARQUIS
3L2Z-78611D70-AB	MARINER
3L2Z-78611D70-AB	MONTEREY
3L2Z-78611D70-AB	NAVIGATOR
3L2Z-78611D70-AB	RANGER
3L2Z-78611D70-AB	SABLE
3L2Z-78611D70-AB	TAURUS
3L2Z-78611D70-AB	TOWN CAR
3L2Z-78611D70-AB	WINDSTAR
3L2Z-78611D70-AB	AVIATOR, EXPLORER 4DR/MOUNTAINEER (BUILT BEFORE 6/25/2004 FOR FRONT SEAT, OR BUILT BEFORE 10/22/2004 FOR REAR SEAT)

NOTE

THE LABOR OPERATIONS WITHIN THIS TSB CAN BE CLAIMED IN COMBINATION AS NEEDED TO COVER THE REQUIRED REPAIRS.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.

TSB 04-24-21 (Continued)

WARRANTY STATUS: Eligible Under Provisions Of
New Vehicle Limited
Warranty Coverage

OPERATION	DESCRIPTION	TIME
042421A	Install Teflon Tape B Pillars Both Sides (Includes Time To Remove And Install Trim Panels If Necessary)	0.8 Hr.
042421B	Install Teflon Tape C Pillars Both Sides (Includes Time To Remove And Install Trim Panels And Seats If Necessary)	1.1 Hrs.

042421C	Install Teflon Tape D Pillars Both Sides (Includes Time To Remove And Install Trim Panels If Necessary)	0.7 Hr.
---------	---	---------

DEALER CODING

BASIC PART NO.
70611D70

CONDITION
CODE
41