

**TRANSMISSION—E4OD—ORANGE TAG ON  
TRANSMISSION PAN—“DO NOT SERVICE”—  
SERVICE PROCEDURES**

**Article No.  
94-16-22**

**FORD:** 1994 BRONCO, ECONOLINE, F-150, F-250, F-350, F-47, F-53, F-59

**ISSUE**

Some E4OD transmissions built after 6/20/94 have a revised material in the torque converter hub seal. An orange tag has been placed on the bottom of the transmission pan stating “Do Not Service”. See Figure 1.

**ACTION**

If a leak is observed from the torque converter hub seal, call [1-800-543-8742](tel:1-800-543-8742) for further instructions. If a service concern is not related to the torque converter hub seal, it is not necessary to contact Ford Motor Company. Perform normal diagnostics as indicated in the appropriate Service Manual Section and repair the transmission as required.

**NOTE**

**DO NOT REMOVE THE ORANGE TAG LOCATED ON THE BOTTOM OF THE TRANSMISSION PAN.**

**OTHER APPLICABLE ARTICLES:** 94-6-17,  
94-9-17

**WARRANTY STATUS:** INFORMATION ONLY

**OASIS CODES:** 504000



Figure 1 - Article 94-16-22