


~~High pressure pumps with oil leaks at the fittings for the high pressure lines and the lugs at the rear can be repaired in the field using the following Ford part number 2C3Z-9G804-AA kit per TSB 03-17-01. This kit contains 3 o-rings, sealant, instructions on how to clean and seal the fittings. Torque specs. for the fittings are also included.~~

~~**Note:** Threads must be cleaned, sealant applied to the first 3 threads at the fittings and plug tightened to proper specs.~~

Pump Operation



The IPR acts to increase ICP by restricting the path to drain.