

**TRANSMISSION—C6, E4OD, AOD, 4R70W—LOW
TRANSMISSION FLUID LEVEL AND/OR SHIFT
AND/OR ENGAGEMENT CONCERNS—4X4 AND AWD
VEHICLES ONLY**

**Article No.
97-12-13**

FORD: 1987-1996 BRONCO
1987-1997 F-150, F-250, F-350
1996-1997 EXPLORER
1997 EXPEDITION

MERCURY: 1997 MOUNTAINEER

This TSB article is being republished in its entirety to include 1997 model year vehicles.

ISSUE

The transmission may have low fluid level and/or may have either a shift concern and/or an engagement concern. This may be caused by transmission fluid leaking from the transmission into the transfer case through the transfer case input seal.

ACTION

Replace the transfer case input seal. The new seal should reduce the possibility of fluid leaking from the transmission into the transfer case. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Check the transmission fluid level. If the transmission fluid level is low and there are no visible signs of a leak, check the transfer case fluid level. The level of fluid in the transfer case should be just below the fill plug hole.
2. If the transfer case fluid level is overfull and the transmission fluid is not burnt, remove the transfer case from the vehicle following the procedure outlined in the appropriate model/year Service Manual.
3. Remove the transfer case input seal. Clean the seal bore in the transfer case.
4. Install a new Transfer Case Input Seal (F77Z-7B215-AA).

5. If the transmission fluid is burnt, repair the transmission as required and then replace the transfer case seal as outlined in Step 3.

PART NUMBER	PART NAME
F77Z-7B215-AA	Transfer Case Input Seal

OTHER APPLICABLE ARTICLES: NONE

SUPERSEDES: 96-20-18

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
971213A	Replace Transfer Case Input Seal - 1987-96 F-150-350, Bronco And 1997 F-250-350	1.6 Hrs.
971213B	Replace Transfer Case Input Seal - 1996-97 Explorer AWD And 1997 Mountianeer	2.7 Hrs.
971213C	Replace Transfer Case Input Seal - 1997 F-150, Expedition	2.1 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
7B215	D8
OASIS CODES: 501000, 502000, 503000, 504000, 508000, 510000	